

Minimum Amperage	45	65	95	125
Maximum Amperage	70	95	130	165

Welding Techniques: Weld at minimum amperage to maintain low heat input.

Welding Positions: Flat, Horizontal, Vertical up, Overhead