Selectrode Industries. Inc.

**S**afety Latest Revision: May 2017

**D**ata Page 1 of 8

# 

## 1. PRODUCT AND COMPANY IDENTIFICATION:

PRODUCT NAME: 1190, 1191, 1193, 1194, 1195, 1196, 1197, 1198

**MANUFACTURER:** Selectrode Industries, Inc.

230 Broadway

Huntington Station, NY 11746 U.S.A.

Phone: 631-547-5470 Fax: 631-547-5475

E-mail: info@selectrode.com

**EMERGENCY TELEPHONE NUMBER**: 631-547-5470

## 2. HAZARD IDENTIFICATION:

Sheet

**Emergency Overview:** This product is normally not considered hazardous as shipped. Avoid eye contact or inhalation of dust from the product. When this product is used in a welding process, the most important hazards are welding fumes, heat, radiation and electric shock.

Classification of the Substance/Mixture

## CLP/GHS Classification (1272/2008):

Acute Toxicity - Inhalation, Category 4

Specific Target Organ Toxicity (Repeated Exposure), Category 1

Hazardous to the Aquatic Environment – Long-Term Hazard, Category 3

## EU Classification (67/548/EEC):

Toxic (T), Harmful (Xn), Dangerous for the Environment (N), R48/23/25, R20, R51/53

Hazardous Classification per 29CFR 1910.1200 (Rev. July 1, 2012):

Acute Toxicity - Inhalation, Category 4

Specific Target Organ Toxicity (Repeated Exposure), Category 1

Hazardous to the Aquatic Environment – Long-Term Hazard, Category 3

Labelling:

Symbols:





**Signal Word:** Danger **Hazard Statements: H332** – Harmful if inhaled.

**H372** – Cause damage to respiratory system, eyes, kidney, brain and nervous system through prolonged or repeated exposure.

**H412** – Harmful to aquatic life with long lasting effects.

## **Precautionary Statements:**

**P210** – Keep away from heat/sparks/open flames/hot surfaces – No smoking.

**P260** – Do not breathe dust/fume/gas/mist/vapours/spray.

P264 - Wash skin and hair thoroughly after handling.

**P270** – Do not eat, drink or smoke when using this product.

**P271** – Use only outdoors or in a well-ventilated area.

**P273** – Avoid release to the environment.

**P280** – Wear protective gloves/eye protection/face protection.

P304+P340 – IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.

P312 - Call a POISON CENTER or doctor/physician if you feel unwell.

**P314** – Get medical advice/attention if you feel unwell.

**S**afety Latest Revision: May 2017 **D**ata Page 2 of 8

**S**heet Selectrode Industries, Inc.

**P402+P404** – Store in a dry place. Store in a closed container.

**P501** – Dispose of contents/container in accordance with local/regional/national/international regulations.

# 3. COMPOSITION / INFORMATION ON INGREDIENTS:

. CONIFOS	ITION / INF	OKIVIA		IGNEDILIN	10.	1		1
Chemical Identity	CAS#	Range %	OSHA PEL (mg/m3)	ACGIH-TLV (mg/m3)	Carcinogenicity	EU Classification (67/548/EEC)	CLP/GHS Classification (1272/2008)	Hazardous Classification per 29CFR 1910.1200 (Rev. July, 2012)
Potassium Chloride	7447-40-7	10-20	NR	NR	No	Not Dangerous	Not Hazardous	Not Hazardous
Sodium Chloride	7647-14-5	10-20	NR	NR	No	Not Dangerous	Not Hazardous	Not Hazardous
Aluminum Fluoride	7784-18-1	1-11	2.5 (as F)	2.5 ( as F )	No	xn) R22, xi) R36/37/38	(H302) Acute Tox. 4 ❖ (H315) Skin Irrit 2 ❖ (H319) Eye Irrit 2A ❖ (H335) STOT SE 3 ❖	(H302) Acute Tox. 4 (*) (H315) Skin Irrit 2 (*) (H319) Eye Irrit 2A (*) (H335) STOT SE 3 (*)
Lithium Cryolite	13821-20-0	10-20	2.5 (as F)	2.5 (as F)	No	X(Xn) R20 (T) R48/23/25 (N),R51/53	(H332) Acute Tox. 4 (**) (H372) STOT RE 1 (**) (H411) Aquatic C. 2 (**)	(H332) Acute Tox. 4 ◆ (H372) STOT RE 1 ◆ (H411) Aquatic C. 2 ◆
Potassium Cryolite	13775-52-5	1-11	2.5 ( as F )	2.5 ( as F )	No	X <sub>1</sub> (x <sub>1</sub> ) R36/37/38	(H315) Skin Irrit 2 ◆ ↑ (H319) Eye Irrit 2A ◆ ↑ (H335) STOT SE 3 ◆ ↑	(H315) Skin Irrit 2
#Aluminum	7429-90-5	45-55	15	10	No	F) R11 – R15	(H228) Flam. Sol. 2 (H261) Water- react. 3	(H228) Flam. Sol 2 (H261) Water- react. 3
Silicon	7440-21-3	0-10	5 (as SiO2)	3 (as SiO2)	No	(F) R11	(H228) Flam. Sol. 2	(H228) Flam. Sol

Important This section covers the materials of which the products manufactured. The fumes and gases produced during normal use of this product are covered in section 10. The term "Hazardous" in "Hazardous Material" should be interpreted as a term required and defined in OSHA Hazard Communication Standard 29CFR 1910-1200 and it does not necessarily imply the existence of hazard. The chemicals or compounds reportable by Section 313 of SARA are marked by the symbol #.

## 4. FIRST AID MEASURES:

**Inhalation**: Remove to fresh air immediately or administer oxygen. Get medical attention immediately. **Skin**: Flush skin with large amounts of water. If irritation develops and persists, get medical attention.

**Eye:** Flush eyes with water for at least 15 minutes. Get medical attention.

**Ingestion:** Obtain medical attention immediately if ingested.

**Electric Shock:** Disconnect and turn off the power. Use a nonconductive material to pull victim away from contact with live parts or wires. Immediately contact a physician.

**S**afety Latest Revision: May 2017

Data
Page 3 of 8
Sheet
Selectrode Industries, Inc.

## 5. FIRE-FIGHTING MEASURES:

**Suitable Extinguishing Media:** Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Welding arcs and sparks can ignite combustible and flammable materials. Use the extinguishing media recommended for the burning material and fire situation.

Unsuitable Extinguishing Media: Do not use water on molten metal. Large fires may be flooded with water from a distance

**Specific Hazards Arising From Chemical:** Hydrogen chloride gas, Potassium oxides, Hydrogen fluoride, Aluminum oxide, Silicon oxides

**Protective Equipment:** Fire fighters should wear complete protective clothing including self-contained breathing apparatus.

## **6. ACCIDENTAL RELEASE MEASURES:**

Personal Precautions: Refer to section 8.
Environment Precautions: Refer to section 13.

**Cleaning Measures:** Solid objects may be picked up and placed into a container. Liquids or pastes should be scooped up and placed into a container. Wear proper protective equipment while handling these materials. Do not discard as refuse.

## 7. HANDLING AND STORAGE:

**Precautions for Safe Handling:** Handle with care to avoid stings or cuts. Wear gloves when handling welding consumables. Avoid exposure to dust. Do not ingest. Some individuals can develop an allergic reaction to certain materials. Retain all warning and identity labels.

**Conditions for Safe Storage:** Store in dry place in closed packages. Keep separate from chemical substances like acids and strong bases, which could cause chemical reactions.

## 8. EXPOSURE CONTROLS/ PERSONAL PROTECTION:

**Engineering Controls:** Avoid exposure to welding fumes, radiation, spatter, electric shock, heated materials and dust. Ensure sufficient ventilation, local exhaust, or both, to keep welding fumes and gases from breathing zone and general area. Keep work place and protective clothing clean and dry. Train welders to avoid contact with live electrical parts and insulate conductive parts. Check condition of protective clothing and equipment on a regular basis.

**Exposure limits:** Use industrial hygiene equipment to ensure that exposure does not exceed applicable national exposure limits. The limits defined under section 3 can be used as guidance. Unless noted, all values are for 8 hour time weighted average. For information about welding fume analysis refer to section 10.

Biological limits: No available data

Personal protection:

**Respiratory protection:** Use an air purifying dust respirator when welding or brazing in a confined space, or when local exhaust or ventilation is not sufficient to keep exposure values within safe limits.

**Hands protection:** Wear appropriate gloves to prevent skin contact.

EN 12477: Protection gloves for welders

Requirements Levels)	(EN	Type A	Type B
Abrasion (Cycles)		2 (500)	1 (100)
Cut (Factor)		1 (1.2)	1 (1.2)
Tear (Newton)		2 (25)	1 (10)
Puncture (Newton)		2 (60)	1 (20)
Burning Behaviour		3	2
Contact Heat		1	1
Convective Heat		2	-
Small Splashes		3	2
Dexterity		1 (11)	4 (6.5)

**S**afety Latest Revision: May 2017 **D**ata Page 4 of 8

Sheet Selectrode Industries, Inc.

# 

Type B gloves are recommended when high dexterity is required as for TIG welding, while type A gloves are recommended for other welding processes. The contact temp (°C) is 100 and the threshold time (seconds) >15.

**Eyes protection:** Welder's helmet or face shield with colour absorbing lenses. Shield and filter to provide protection from harmful UV radiation, infra red and molten metal approved to standard EN379. Filter shade to be a minimum of shade 9.

**Skin protection:** Heat-resistant protective clothing. Wear safety boots, apron, arm and shoulder protection. Keep protective clothing clean and dry. Clothing should be selected to suit the level, duration and purpose of the welding activity.

	Class 1		
Impact of Spatter	15 Drops		
Heat Transfer (radiation)	RHTI 24 ≥ 7 seconds		
Process	Manual welding with light formation of spatter and drops     Gas Welding     TIG Welding     MIG Welding     Micro plasma welding     Brazing     Spot Welding     MMA Welding (with rutile-covered electrode)		
Environmental Conditions	Operation of machines  Oxygen cutting machines  Plasma cutting machines  Resistance welding machines  Machines for thermal spraying  Bench welding		

	Class 2		
Impact of Spatter	25 Drops		
Heat Transfer (radiation)	RHTI 24 ≥ 16 seconds		
Process	Manual welding with heavy formation of spatter and drops  MMA welding (with basic or cellulose-covered electrodes)  MAG welding (with CO2 or mixed gases)  MIG Welding (with high current)  Self shielded flux core arc welding  Plasma cutting  Gouging  Oxygen cutting  Thermal spraying		
Environmental Operation of machines			
Conditions	<ul> <li>In confined spaces</li> <li>At overhead welding/cutting or in comparable constrained positions</li> </ul>		

# 9. PHYSICAL AND CHEMICAL PROPERTIES:

Appearance: Solid.

Color: 1190/White 1191/White 1193/ White 1194/Lt. Green 1195/ Blue 1196/ Blue 1197/ Green 1198/ White

**Odour:** Odourless

**Odour Threshold:** Not Available

pH Value: Not Available

Melting Point/Melting Range: 1220° F, 660° C

**S**afety Latest Revision: May 2017

**D**ata Page 5 of 8

Sheet Selectrode Industries, Inc.

# 

Freezing Point: Not Available

Boiling Point/Boiling Range: 4566° F, 2519° C

Flash point: Not Available
Evaporation Rate: Not Available
Self-in flammability: Not Available
Explosion limits: Not Available
Vapour pressure: Not Available
Vapour density: Not Available
Density at 20°C: Not Available
Relative density: 6-9 g/cm3
Solubility: Insoluble in water.

Partition coefficient: Not Available
Auto-ignition temperature: Not Available
Decomposition temperature: Not Available

Other Information: No available data.

\_\_\_\_\_

## 10. STABILITY AND REACTIVITY:

**Chemical Stability:** This product is stable under normal conditions.

Hazardous Reactions: Contact with chemical substances like acids or strong bases cause generation of gas.

Conditions to Avoid: Not applicable.
Incompatible Materials: Reacts with acid.

**Hazardous Decomposition Products:** When this product is used in a welding process, hazardous decomposition product would include those from volatilization, reaction or oxidation of the material listed in section 3 and those from the base metal and coating. The amount of fumes generated from this product varies with welding parameters and dimensions.

Refer to applicable national exposure limits for fume compounds, including those exposure limits for fume compounds found in section 3. Reasonably expected gaseous products would include carbon oxides, nitrogen oxides and ozone. Air contaminants around the welding area can be affected by the welding process and influence the composition and quality of fumes and gases produced.

## 11. TOXICOLOGICAL INFORMATION:

**Signs and Symptoms of Overexposure:** Inhalation of welding fumes and gases can be dangerous to your health. Classification of welding fumes is difficult because of varying base materials, coatings, air contaminants and processes. The Internal Agency for Research on Cancer has classified welding fumes as possible carcinogenic to humans (Group 2B).

**Acute Effects:** Overexposure to welding fumes may result in symptoms like metal fume fever, dizziness, nausea, dryness or irritation of the nose, throat or eyes. Signs and symptoms of Potassium Chloride exposure are hyperkalaemia, nausea, vomiting, abdominal pain, diarrhoea, constipation, paraesthesia, thirst, dizziness, rash, pruritus, weakness, muscle cramps, minor psychiatric changes and minor visual changes. May cause sensitisation by skin contact

LD/LC50 Values that are relevant for classification		
Potassium Chloride 7447-40-7		
	LC50	880 mg/l (96h) (fathead minnow)

LD/LC50 Values that are relevant for classification			
Aluminum Fluoride 7784-18-1			
Oral	LD50	1800 mg/kg (rat)	
	LC50	8.4 mg/l (3d) (fresh water algae)	

LD/LC50 Values that are relevant for classification
Aluminum 7429-90-5

**S**afety Latest Revision: May 2017

**D**ata Page 6 of 8

**S**heet Selectrode Industries, Inc.

# 

Oral	LD50	>15900 mg/kg (rat)
Inhalation	LC50	>.888 mg/L/4 hr. (rat)
	LC50	.12 mg/l (96h) (rainbow trout)

LD/LC50 Values that are relevant for classification		
Silicon 7440-21-3		
Oral	LD50	3160 mg/kg (rat)

**Chronic Effects:** Overexposure to welding fumes may affect pulmonary function.

## 12. ECOLOGICAL INFORMATION:

**Toxicity:** Welding rods contain metals which are considered to be very toxic towards aquatic organisms. Finely divided welding rods are therefore considered harmful to aquatic organisms.

**Persistence and Degradability:** The welding rods consist of elements that can not degrade any further in the environment. **Bio accumulative Potential:** Welding rods contain heavy metals which bio accumulates in the food chain. The following figures are the bio concentration factor (BCF) for the substances on their own.

BCF:

Aluminum, BCF: 18

**Mobility in Soil:** Welding rods are not soluble in water or soil. Particles formed by working welding rods can be transported in the air.

Other Adverse Effects: In massive form, welding rods present no hazards to the aquatic environment.

Welding materials could degrade into components originating from the materials used in the welding process. Avoid exposure to conditions that could lead to accumulation in soils or groundwater. Harmful to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

#### 13. DISPOSAL CONSIDERATIONS:

**Product:** For product elimination, consult recycling companies or appropriate local authority. **Package:** May be disposed in approved landfills provided local regulations are observed.

## 14. TRANSPORT INFORMATION:

**UN-number:** Welding rods are not classified as dangerous goods for transport and has no UN number.

**UN proper shipping name:** Welding rods are not classified as dangerous goods for transport and has no UN proper shipping name.

Transport hazard class: Welding rods are not classified as dangerous goods for transport.

**Packing group:** There are not any special precautions with which a user should or must comply or be aware of in connection with transport or conveyance either within or outside premises.

**Environmental hazards:** Welding rods are not environmentally hazardous according to the criteria of the UN Model Regulations (as reflected in the IMDG Code, ADR, RID and AND) and/or a marine pollutant to the IMDG Code.

**Special precautions for users:** There are not any special precautions which a user should or must comply or be aware of in connection with transport or conveyance either within or outside premises of the welding rod.

**Transport in Bulk According to Annex III MARPOL 73/78 and the IBC Code:** Welding rods in massive form do not subject under MARPOL 73/78 and the IBC Code. Not applicable – product is transported only in packaged form.

15. REGULATORY INFORMATION:

Safety, health and environment regulations/legislation specific for the substance or mixture: Read and understand the manufacturer's instructions, your employer's safety practices and the health and safety instructions on the label. Observe any federal and local regulations. Take precautions when welding and protect yourself and others.

**S**afety Latest Revision: May 2017

**D**ata Page 7 of 8

**S**heet Selectrode Industries, Inc.

# 

**Warning:** Welding fumes and gases are hazardous to your health and may damage lungs and other organs. Use adequate ventilation. Electric shock can kill. Arc rays and sparks can injure eyes and burn skin. Wear correct hand, head, eye and body protection.

## Chemical safety assessment: No

USA: Under the OSHA Hazard Communication Standard, this product is considered hazardous.

CALIFORNIA PROPOSITION 65: No compounds present. (California Health & Safety Code § 25249.5 et seq.)

United States EPA Toxic Substance Control Act: All constituents of this product are on the TSCA inventory list or are excluded from listing.

## **EPCRA/SARA Title III Toxic Chemicals**

The following metallic components are listed as SARA 313 "Toxic Chemicals" and potential subject to annual SARA reporting. See Section 3 for weight percentage.

Ingredient Name	Disclosure Threshold
Aluminum	15 mg/m3

#### 16. OTHER INFORMATION:

The information in this document is believed to be correct as of the date issued. However, no warranty is expressed to be implied regarding the accuracy or completeness of this information. This information and product are furnished on the condition that the person receiving them shall make his own determinations as to the suitability of the product for his particular purpose and on the condition that he assumes the risk of his use thereof.

This Material Safety Data Sheet complies with the EC directives 91/155/EEC and 93/112/EEC, including modifications 2001/58/EC.

Complies with OSHA Communication Standard 29 CFR 1910.1200 and Superfund Amendments and Reauthorization Act (SARA) of 1986 Public Law 99-499

#### **Hazard Statements:**

H228 - Flammable solid

**H261** – In contact with water releases flammable gas.

**H302** – Harmful if swallowed.

**H315** – Causes skin irritation.

H317 – May cause an allergic skin reaction.

H319 – Causes serious eve irritation.

H332 – Harmful if inhaled.

**H335** – May cause respiratory irritation.

H372 – Causes damage to organs through prolonged or repeated exposure.

H400 – Very toxic to aquatic life

## **R-Phrases:**

**R11** – Highly flammable

R15 – Contact with water liberates extremely flammable gases.

**R20** – Harmful by inhalation.

**R22** – Harmful if swallowed.

R36/37/38 – Irritating to eyes, respiratory system and skin.

R48/23/25 – Toxic: danger of serious damage to health by prolonged exposure through inhalation.

R51/53 – Toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

#### S-Phrases:

**S16** – Keep away from source of ignition – No smoking.

**S22** – Do not breathe dust.

**S26** – In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

\$36/37/39 – Wear suitable protective clothing, gloves and eye/face protection.

**S43** – In case of fire, use fire-fighting equipment on basis class D.

S45 – In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible).

**S61** – Avoid release to the environment.

**S**afety Latest Revision: May 2017

**D**ata Page 8 of 8

**S**heet Selectrode Industries, Inc.

End of the document.